## invaero®

CIRRUS SR 22 SN 0588 CIRRUS SR 22
SN 0588
2003
REGISTRATION D-ENNN
TTAF APPROX 925 HRS







## invaero®

CIRRUS SR 22 SN 0588









CIRRUS SR 22 SN 0588

GENERAL

MAINTENANCE

AVIONICS

> 2003

> Registration D-ENNN

> SN 0588

>TTAF 925 hrs

> Total Landings 1010

> 2 owners since new

> Engine IO-550-N Continental TTSN 925 hrs installed 2003

> Propeller Hartzell PHC-J3YF-1RF/F7693DFB TTSO 2 hrs overhauled 12/2024

> last 100 hrs Inspection at 925 hrs in 12/2024

> Parachute Replacement in 01/2025

> no damage history

Major maintenance work carried out in 12/2024 with 925 flight hours:

> L/H and R/H Magneto Overhauled

> Ice Protection System Filter replaced

> Fuel Boost Pump replaced

> Battery Nr.1 and 2 replaced

> Propeller Overhaul performed

> Propeller Governor Overhaul performed

> Fire Extinguisher replaced

> Engine Fuel Pump replaced

> Brake Discs replaced

> AVIDYNE EXC 5000C Multi - Function Display

> STEC 55 X Autopilot

> COM/NAV Dual X Garmin GNS 430

> DME King KN 62a

> ELT Ameri-King AK-45 I Battery replaced 12/2024

> Transponder Garmin GTX 330 Mode-S

> Audio Panel Garmin GMA 340

> SANDEL HSI

> Stormscope L3 WX 500

>TCAS L 3 SKY 497

> Moving Terrain



CIRRUS SR 22 SN 0588

INTERIOR

EXTERIOR

ADDITIONAL EQUIPMENT

- > Executive 4 Passengers
- > cream leather seats with matching coloured carpets and alcantara interior new in 2011
- > Overall White with Blue & Grey accent stripes
- > Cirrus Airframe Parachute System (CAPS) new in 01/2025
- > Propeller de-ice
- > TKS System

ASKING PRICE

MAKE OFFER (VAT APPLICABLE)

Specification subject to verification at inspection. Cirrus SR 22 offered subject to prior sale and may be withdrawn from the market without prior notice.

invaero GmbH & Co. KG Am Rübgarten 2 • D-57299 Burbach / Germany +49 (0)2736 4498601 Info@invaero.de

www.invaero.de