invaero®

LEARJET 45 XR BOMBARDIER LEARJET 45 XR
2008
SN 45.372
REGISTRATION SE- RMO
AFTT 2.981 HRS
LANDINGS 2.379







invaero[®]













LEARJET 45 XR BOMBARDIER

GENERAL

- > Year of manufacture 2008
- > S/N 45-372
- > AFTT 2981 HRS / 2.379 Landings
- > Registration SE- RMO
- > Executive 9 Passengers
- > 3 Owners since new
- > Always hangared
- > EASA Part 145 maintained
- > CAMP (Computerized Aircraft Maintenance Program)

> Jet Support Services, Inc. - JSSI on Engine and APU

- > MPI Inspection c/w in 10/2019
- > Engine TBO upgraded to 7000 hours

M A I N T E N A N C E P R O G R A M M

INTERIOR

- > Executive/9 Passengers
- > light beige interior in good condition
- > double club seating, jumpseat
- > brown leather sidewalls
- > forward refreshment center
- > warming oven
- > dual hot water containers
- > brown veneer woodwork
- > entertainment system w/DVD Player & CD changer
- > Airshow 410
- > forward / aft 12.1 inch LCD monitors
- > subwoofer
- > brushed aluminium hardware
- > belted aft lavatory

EXTERIOR

> Gray metallic w/white & dark stripes

INSTALLED ACCESSORIES

- > Flight Data Recorder
- > Dual Flight Management Systems
- > Cockpit Voice Recorder
- > ADS-B OUT + LPV approved (in progress)
- > Terrain Awareness & Warning System
- >RVSM
- > Traffic Collision Avoidance System
- > Emergency Locator Transmitter

APU

- > Honeywell RE-100
- >S/N P-410
- >TSN 1.134 hrs
- > Jet Support Service, Inc. (JSSI)

www.invaero.de

invaero[®]

LEARJET 45 XR BOMBARDIER

AVIONICS PACKAGE ADF CVR DME FDR F M S ΗF NAVRADAR ATIMETER SATPHONE TAWS TCAS XPDR WEATHER RADAR **ELT**

- > Honeywell Primus 1000
- > Dual Honeywell RNZ 851
- > Honeywell SSCVR (120 MINUTES)
- > Dual Honeywell RNZ-851
- >L3 FA-2100
- > Dual Universal UNS-1E/WAAS
- > Dual Primus HF 1050 w/SELCAL
- > Dual Honeywell RNZ-851
- > Honeywell RT-300
- > Iridium w/cockpit & cabin handsets
- > Honeywell Mark V EGPWS
- > Honeywell TCAS-200 TCAS-II w/ch 7.1
- > Dual Honewell RCZ-833k enhanced Mode S
- > Honeywell Primus WU-660
- > Artex C406-2
- > Autopilot
- > Flight Director
- >RVSM

ADDITIONAL EQUIPMENT

- > ADS-B Out + LPV approved (in progress)
- >XM wather
- > dual angle of attack indicators

ENGINE

>TFE731-20BR-1B

>S/N Engine 1	P116969C	Engine 2	P116968C
>TTSN	2.981 hrs		2.981 hrs
>TBO/TBCI	7.000 hrs		7.000 hrs
>TCSN	2.375		2.375

> Jet Support Service, Inc. (JSSI)

INSPECTION STATUS

- > Engine MPI Inspection c/w in October 2019
- > A, B & C Inspection c/w in October 2019

Specification subject to verification at inspection. Learjet 45 XR offered subject to prior sale and may be withdrawn from the market without prior notice.

invaero GmbH & Co. KG

Am Rübgarten 2 • D-57299 Burbach / Germany +49 (0)2736 4498601 Info@invaero.de